#### SAFETY DATA SHEET

**EPS 4000 ELECTROPOLISH** 

Product ID: EP400001 Revised: 04-27-2022 Replaces: 01-13-2015

# 1. IDENTIFICATION

Product Identifier:

**EPS 4000 ELECTROPOLISH** 

Other Identifiers:

N.A. Mixture

CAS Number: Recommended Use:

No data available.

Restrictions on Use:

No data available.

Electro Polish Systems, Inc. W175 N11117 Stonewood Dr.

EMERGENCY RESPONSE NUMBERS: CHEMTREC Emergency #: (800) 424-9300

Suite 101

Germantown, WI 53022

(262) 293-9970 (800) 959-0868

# 2. HAZARD(S) IDENTIFICATION

GHS Classification(s): Substance or mixture corrosive to metals Category 1

Skin Corrosion/Irritation Category 1B

Serious Eye Damage/Eye Irritation Category 1

Carcinogenicity Category 1A

Acute Toxicity - Inhalation Vapour Category 2

Specific Target Organ Systemic Toxicity (STOT) - Repeated Exposure Category 2

Acute Toxicity - Inhalation Dust / Mist Category 3

**GHS Label Elements:** 

**GHS Hazard Symbols:** 







Signal Word:

Danger

**Hazard Statements:** 

May be corrosive to metals.

Causes severe skin burns and eye damage.

Fatal if inhaled. Toxic if inhaled. May cause cancer.

May cause damage to organs (teeth, respiratory system) through prolonged or repeated

exposure (by inhalation).

**Precautionary Statements:** 

**Prevention:** Obtain special instructions before use.

Do not handle until all safety precautions have been read and understood.

Keep only in original container.

Do not breathe dust/fume/gas/mist/vapours/spray.

Wash thoroughly after handling.

Use only outdoors or in a well-ventilated area.

Wear protective gloves/protective clothing/eye protection/face protection.

Wear respiratory protection.

#### EPS 4000 ELECTROPOLISH Product ID: EP400001

Response: IF SWALL

IF SWALLOWED: Rinse mouth. Do NOT induce vomiting.

IF ON SKIN (or hair): Take off immediately all contaminated clothing. Rinse skin with

water.

IF INHALED: Remove victim to fresh air and keep at rest in a position comfortable

for breathing.

IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses,

if present and easy to do. Continue rinsing.

Immediately call a POISON CENTER or doctor/physician.

Specific treatment is urgent (see on this label). Wash contaminated clothing before reuse. Absorb spillage to prevent material damage.

Storage:

Store in a well-ventilated place. Keep container tightly closed.

Store in a secure manner.

Store in corrosive resistant container with a resistant inner liner.

Disposal:

Dispose of in accordance with local, regional and international regulations.

Hazards Not Otherwise Classified:

May react with certain metals to form explosive/flammable hydrogen

gas. May react violently with water.

Percentage of Components with Unknown Acute Toxicity:

Dermal:

42.4 %

# 3. COMPOSITION/INFORMATION ON INGREDIENTS

#### Substances/Mixtures:

 Chemical or Common Name/Synonyms
 CAS Number
 % by Wt.

 Phosphoric Acid
 7664-38-2
 < 70 %</td>

 Sulfuric Acid
 7664-93-9
 < 70 %</td>

Note: Any chemical identity and/or exact percentage not expressly stated is being withheld as a trade secret or is due to batch variation.

## 4. FIRST-AID MEASURES

#### **Description of Necessary Measures:**

**Eye Contact:** If in eyes: Immediately flush eyes with plenty of water for at least 15 minutes while holding eyelids open. Tilt head to avoid contaminating unaffected eye. Get immediate medical attention. Remove contact lens if easy to do.

**Skin Contact:** If on skin: Immediately flush skin with plenty of water for at least 15 minutes while removing contaminated clothing and shoes. Get medical attention immediately. Do not reuse clothing and shoes until cleaned. Do not apply oils or ointments unless ordered by the physician. Discard contaminated leather articles such as shoes and belt.

**Inhalation:** If inhaled: Remove to fresh air. If breathing is difficult, administer oxygen. If not breathing, give artificial respiration, preferably mouth-to-mouth. GET MEDICAL ATTENTION IMMEDIATELY. DO NOT use mouth-to-mouth method if victim ingested or inhaled the substance; induce artificial respiration with the aid of a pocket mask equipped with a one-way valve or other proper respiratory medical device.

**Ingestion:** If swallowed: If fully conscious, drink a quart of water. DO NOT induce vomiting. CALL A PHYSICIAN IMMEDIATELY. If unconscious or in convulsions, take immediately to a hospital or a physician. NEVER induce vomiting or give anything by mouth to an unconscious victim. If vomiting occurs spontaneously, keep head below hips to prevent aspiration of liquid into the lungs.

#### Most Important Symptoms/Effects, Acute and Delayed:

**Eye Contact:** CORROSIVE-Causes severe irritation and burns. May cause: ulcerations. conjunctivitis. permanent eye damage. blindness. blurred vision. redness. pain. tissue destruction.

Page: 2 of 8

**Skin Contact:** CORROSIVE-Causes severe irritation and burns. Contact may cause: dermatitis (inflammation of the skin). ulceration. permanent skin damage. Concentrated solutions may cause: severe burns. severe necrosis. Prolonged and repeated exposure to dilute solutions may cause irritation, redness, pain and drying and cracking of the skin.

Skin Absorption: No data available.

Inhalation: CORROSIVE-Causes severe irritation and burns. Vapors or mists may irritate or burn: respiratory tract. nose. mouth. throat. May cause: persistent coughing. pulmonary edema. chemical pneumonitis. permanent damage. Vapors or mists may damage: mucous membranes. Vapors or mists may cause: coughing. sore throat. shortness of breath. labored breathing. choking. bronchospasms. death. Effects may be delayed. Chronic exposure may cause: dental erosions, discoloration of teeth. bronchitis. bronchial emphysema.

**Ingestion:** CORROSIVE-Causes severe irritation and burns. May cause damage to the: mouth. throat. esophagus. stomach. gastrointestinal tract. May cause: pain. vomiting. diarrhea. bleeding. labored breathing. burns or perforation of the gastrointestinal tract leading to ulceration and secondary infection. death. Effects may be delayed. Aspiration into the lungs may cause chemical pneumonia and lung damage.

Indication of Immediate Medical Attention and Special Treatment Needed: This product contains materials that may cause severe pneumonitis if aspirated. If ingestion has occurred less than 2 hours earlier, carry out careful gastric lavage; use endotracheal cuff if available, to prevent aspiration. Observe patient for respiratory difficulty from aspiration pneumonitis. Give artifical resuscitation and appropriate chemotherapy if respiration is depressed. Following exposure the patient should be kept under medical review for at least 48 hours as delayed pneumonitis may occur. DO NOT attempt to neutralize the acid with weak bases since the reaction will produce heat that may extend the corrosive injury.

## 5. FIRE-FIGHTING MEASURES

**Extinguishing Media:** Not flammable or combustible. For fires in area use appropriate media. For example: Water spray. Dry chemical. Carbon dioxide. Foam.

#### Specific Hazards Arising from the Chemical:

**Fire and Explosion Hazards:** Product may react with some metals (ex.: Aluminum, Zinc, Tin, etc.) to release flammable hydrogen gas. Will react with organic materials with evolution of heat and sulfur dioxide. Concentrated acid is a strong oxidizing agent. May cause ignition of combustible materials on contact with generation of sulfur dioxide fumes.

**Hazardous Combustion Products:** Phosphorous oxides. Phosphine. Toxic vapors. Corrosive vapors. Sulfur oxides.

Special Protective Equipment and Precautions for Fire-Fighters: Evacuate area of unprotected personnel. Wear protective clothing including NIOSH-approved self-contained breathing apparatus. Remain upwind of fire to avoid hazardous vapors and decomposition products. Use water spray to cool fire-exposed containers. Do not get water inside containers. Product generates heat upon addition of water, with possible spattering. Neutralize run-off with Lime, Soda Ash, etc., to prevent corrosion of metals and formation of Hydrogen gas. Run-off from fire control may cause pollution.

### 6. ACCIDENTAL RELEASE MEASURES

**Personal Precautions, Protective Equipment, Emergency Procedures:** CORROSIVE MATERIAL. Evacuate unprotected personnel from area. Maintain adequate ventilation. Follow personal protective equipment recommendations found in Section 8. Never exceed any occupational exposure limit.

**Methods and Materials for Containment and Clean Up:** Contain spill, place into drums for proper disposal. Soak up residue with inert absorbent material. Place in non-leaking containers for immediate disposal. Flush remaining area with water and neutralize with Soda Ash, Lime or Limestone and dispose of properly. Adequate ventilation is required if soda ash is used, because of the consequent release of carbon dioxide gas. Avoid direct discharge to sewers and surface waters. Notify authorities if entry occurs.

Page: 3 of 8

# 7. HANDLING AND STORAGE

Precautions for Safe Handling: Avoid contact with eyes, skin, and clothing. Use with adequate ventilation. Do not swallow. Avoid breathing vapors, mists, or dust. Do not eat, drink, or smoke in work area. Wash thoroughly after handling. Empty containers retain product residue (vapor, dust, or liquid) and can be dangerous. DO NOT pressurize, cut, weld, braze, solder, drill, grind, or expose such containers to heat, flame, sparks, static electricity, or other source of ignition. They may explode and cause injury or death. CORROSIVE MATERIAL. Contact with water may cause violent reaction with evolution of heat. To dilute: Add product slowly to lukewarm water; not water to product. Mixing with strong bases can cause high heat of reaction and generate steam. Ground lines and equipment used during transfer to reduce the possibility of static spark-initiated fire or explosion. Use non-sparking tools.

Conditions for Safe Storage, Including any Incompatibilities: CORROSIVE MATERIAL. Store in a cool, well ventilated area, out of direct sunlight. Store in a dry location away from heat. Keep away from incompatible materials. Keep containers tightly closed. Do not store in unlabeled or mislabeled containers. Do not freeze. Highly corrosive to most metals with evolution of hydrogen gas. Explosive/flammable concentrations of hydrogen gas may accumulate inside metal containers. Elevated temperatures will increase the corrosion rate of most metals.

# 8. EXPOSURE CONTROLS/PERSONAL PROTECTION

**OSHA Exposure Guidelines:** 

<u>Component</u> <u>Limits</u>

Phosphoric Acid 1 mg/m3 TWA Sulfuric Acid 1 mg/m3 TWA

**ACGIH Exposure Guidelines:** 

<u>Component</u> <u>Limits</u>

Phosphoric Acid 1 mg/m3 TWA; 3 mg/m3 STEL
Sulfuric Acid 0.2 mg/m3 TWA (thoracic fraction)

**Engineering Controls:** Local exhaust ventilation, process enclosures, or other engineering controls are required when handling or using this product to avoid overexposure. Maintain adequate ventilation. Do not use in closed or confined spaces. Avoid creating dust or mist. Keep levels below exposure limits. To determine exposure levels, monitoring should be performed regularly.

#### **Individual Protection Measures:**

Eye/Face Protection: Wear chemical safety goggles and a full face shield while handling this product. Do not wear contact lenses.

**Skin Protection:** Prevent contact with this product. Wear gloves and protective clothing depending on condition of use. Protective gloves: Impervious. Chemical-resistant. Acid-proof.

Respiratory Protection: Respiratory protection must be worn if ventilation does not eliminate symptoms or keep levels below recommended exposure limits. If exposure limits are exceeded, wear: NIOSH-Approved respirator. NIOSH-Approved air-purifying respirator with: Acid gas cartridge and Dust/mist filter. NIOSH-Approved positive pressure supplied air respirator. NIOSH-Approved self-contained breathing apparatus. DO NOT exceed limits established by the respirator manufacturer. All respiratory protection programs must comply with OSHA 29 CFR 1910.134 and ANSI Z88.2 requirements and must be followed whenever workplace conditions require a respirator's use.

Other Protective Equipment: Eye-wash station. Safety shower. Rubber apron. Chemical safety shoes. Rubber boots. Protective clothing. Full-rubber acid suit.

**General Hygiene Conditions:** Wash with soap and water before meal times and at the end of each work shift. Good manufacturing practices require gross amounts of any chemical be removed from skin as soon as practical, especially before eating or smoking. Food, beverages, and tobacco products should not be carried, stored or consumed where this material is in use.

#### 9. PHYSICAL AND CHEMICAL PROPERTIES

Physical State: Liquid.

Color: Clear. Colorless to pale pink or vellow.

Odor: No odor. Odor Threshold: N.D.

**pH:** < 1 (as is)

Freezing Point (deg. F): N.D. Melting Point (deg. F): N.D.

Initial Boiling Point or Boiling Range: N.D.

Flash Point: N.A.

Flash Point Method: N.A.

Evaporation Rate (nBuAc = 1): N.D. Flammability (solid, gas): N.D. Lower Explosion Limit: N.A. Upper Explosion Limit: N.A. Vapor Pressure (mm Hg): N.D. Vapor Density (air=1): N.D.

Specific Gravity or Relative Density: 1.750 @ 25 Deg. C

Solubility in Water: Complete

Partition Coefficient (n-octanol/water): N.D.

**Autoignition Temperature:** No Data **Decomposition Temperature:** N.D.

Viscosity: 29 @ 25C % Volatile (wt%): N.D. VOC (wt%): 0

VOC (wt%): 0 VOC (lbs/gal): 0 Fire Point: N.D.

#### 10. STABILITY AND REACTIVITY

Reactivity: No data available.

Chemical Stability: Stable under normal conditions.

Possibility of Hazardous Reactions: Hazardous polymerization will not occur under normal conditions. May react with certain metals to form explosive/flammable hydrogen gas. Mixing with strong bases can cause high heat of reaction and generate steam. Phosphoric acid forms flammable gases with sulfides, mercaptans, cyanides and aldehydes. Phosphoric acid forms toxic fumes with cyanides, sulfides, fluorides, organic peroxides, and halogenated organics. Phosphoric acid mixtures with nitromethane are explosive. Hazardous gases are evolved on contact with chemicals such as cyanides, sulfides, carbides, etc.

Conditions to Avoid: Contact with water may cause violent reaction with evolution of heat. To dilute: Add product slowly to lukewarm water; not water to product. Avoid high temperatures. Avoid contact with heat, sparks, electric arcs, other hot surfaces, and open flames. Contact with organic materials may cause fire and explosions.

Incompatible Materials: Metals. Strong oxidizing agents. Strong reducing agents. Sulfides. Sulfites. Bases. Fluorine. Sulfur trioxide. Phosphorous pentoxide. Sodium tetrahydroborate. Aldehydes. Amines. Amides. Alcohols. Azo-compounds. Carbamates. Esters. Caustics. Phenols. Cresols. Ketones. Organophosphates. Epoxides. Explosives. Combustible materials. Unsaturated halides. Organic peroxides. Mercaptans. Cyanides. Nitromethane. Glycols. Fluorides. Halogenated organics. Sulfur. Aluminum. Copper. Mild steel. Brass. Bronze. Steel. Water. Alkalies. Reducing agents. Carbonates. Carbides. Chlorates. Fulminates. Nitrates. Powdered metals. Organic materials. Nitrogen compounds. Picrates. Halogens. Alkali metals. and many other reactive substances.

# EPS 4000 ELECTROPOLISH Product ID: EP400001

Hazardous Decomposition Products: Phosphorous oxides. Phosphine. Reactions with other materials may liberate toxic and/or explosive gases. Sulfur oxides. Sulfuric acid vapors. Hydrogen gas.

#### 11. TOXICOLOGICAL INFORMATION

Routes of Exposure: Eyes. Skin. Inhalation. Ingestion.

Symptoms/Effects: Acute, Delayed and Chronic:

Eye Contact: CORROSIVE-Causes severe irritation and burns. May cause: ulcerations. conjunctivitis. permanent eye damage. blindness. blurred vision. redness. pain. tissue destruction.

**Skin Contact:** CORROSIVE-Causes severe irritation and burns. Contact may cause: dermatitis (inflammation of the skin). ulceration. permanent skin damage. Concentrated solutions may cause: severe burns. severe necrosis. Prolonged and repeated exposure to dilute solutions may cause irritation, redness, pain and drying and cracking of the skin.

Skin Absorption: No data available.

Inhalation: CORROSIVE-Causes severe irritation and burns. Vapors or mists may irritate or burn: respiratory tract. nose. mouth. throat. May cause: persistent coughing. pulmonary edema. chemical pneumonitis. permanent damage. Vapors or mists may damage: mucous membranes. Vapors or mists may cause: coughing. sore throat. shortness of breath. labored breathing. choking. bronchospasms. death. Effects may be delayed. Chronic exposure may cause: dental erosions. discoloration of teeth. bronchitis. bronchial emphysema.

**Ingestion:** CORROSIVE-Causes severe irritation and burns. May cause damage to the: mouth. throat. esophagus. stomach. gastrointestinal tract. May cause: pain. vomiting. diarrhea. bleeding. labored breathing. burns or perforation of the gastrointestinal tract leading to ulceration and secondary infection. death. Effects may be delayed. Aspiration into the lungs may cause chemical pneumonia and lung damage.

#### **Numerical Measures of Toxicity:**

 Component
 Oral LD50
 Dermal LD50
 Inhalation LC50

 Phosphoric Acid
 Rat: 1530 mg/kg
 Rabbit: 2730 mg/kg
 1H Rat: > 850 mg/m3

Sulfuric Acid Rat: 2140 mg/kg No Data 2H Rat: 510 mg/m3

Acute Toxicity Estimate (ATE): Inhalation Vapor: 1.2028 mg/L Inhalation Dust/Mist: 0.6014 mg/L

**Cancer Information:** 

This product contains 0.1% or more of the following chemicals listed by NTP, IARC or OSHA as known or possible carcinogens:

Sulfuric acid mist

**Medical Conditions Aggravated by Exposure to Product:** Eye disorders. Skin disorders. Impaired respiratory function. Lung disorders. Respiratory system disorders.

Other: Circulatory collapse with clammy skin, weak and rapid pulse, shallow respirations, and scanty urine may follow skin contact or ingestion. Circulatory shock is often the immediate cause of death. The International Agency for Research on Cancer (IARC) has concluded that occupational exposure to strong inorganic acid mists containing sulfuric acid is carcinogenic to man, causing cancer of the larynx (the voice box). Although no direct link has been established between exposure to sulfuric acid itself, and cancer in man, exposure to any mist or aerosol during the use of this product should be avoided.

# 12. ECOLOGICAL INFORMATION

Ecotoxicological Information: No data available.

Chemical Fate Information: No data available.

## 13. DISPOSAL CONSIDERATIONS

Hazardous Waste Number: D002

**Disposal Method:** Dispose of in a permitted hazardous waste management facility following all local, state and federal regulations. Since emptied containers retain product residue, follow label warnings even after container is emptied. DO NOT pressurize, cut, weld, solder, drill, grind or expose empty containers to heat, flame, sparks or other sources of ignition.

# 14. TRANSPORT INFORMATION

#### **DOT (Department of Transportation):**

Identification Number: UN3264

Proper Shipping Name: CORROSIVE LIQUID, ACIDIC, INORGANIC, N.O.S. (CONTAINS PHOSPHORIC

ACID, SULFURIC ACID)

Hazard Class: 8
Packing Group: ||

Label Required: CORROSIVE

Reportable Quantity (RQ): 5000# (Phosphoric Acid); 1000# (Sulfuric Acid)

#### IATA (International Air Transportation Association)

Identification Number:	UN3264				
Proper Shipping Name:	CORROSIVE LIQUID, ACIDIC, INORGANIC, N.O.S. (CONTAINS PHOSPHORIC ACID, SULFURIC ACID)				
Class or Division:	8				
Packing Group:	II .				
Label Required:	CORROSIVE				

## 15. REGULATORY INFORMATION

**TSCA Inventory Status:** All components of this product are on the TSCA Inventory or are exempt from TSCA Inventory requirements.

## SARA Title III Section 311/312 Category Hazards:

Immediate (Acute) Delayed (Chronic)		onic) <u>F</u>	Fire Hazard	Pres	sure Rele	Reactive		
Yes Yes			No	No			Yes	
Regulated Compone	ents:	CAS	CERCLA	SARA	SARA	U.S.	WI	Prop
Component		<u>Number</u>	RQ	<u>EHS</u>	<u>313</u>	<b>HAP</b>	<b>HAP</b>	<u>65</u>
Phosphoric Acid		7664-38-2	Yes	No	No	No	Yes	No
Sulfuric Acid		7664-93-9	Yes	Yes	Yes	No	Yes	Yes

#### \*Prop 65 - May Contain the Following Trace Components:

Sulfur Dioxide

Note: \* Sulfuric acid appears on the Section 313 List. However, the listing only applies to the aerosol forms of

sulfuric acid.

#### 16. OTHER INFORMATION

Hazard Rating System Health: 3\* Flammability: 0

# **EPS 4000 ELECTROPOLISH**

Product ID: EP400001

Reactivity: 2

\* = Chronic Health Hazard

**NFPA Rating System** 

Health: 3 Flammability: 0 Reactivity: 2 Special Hazard: W

SDS Abbreviations N.A. = Not Applicable N.D. = Not Determined HAP = Hazardous Air Pollutant

VOC = Volatile Organic Compound

C = Ceiling Limit

N.E./Not Estab. = Not Established

SDS Prepared by: JAK

Reason for Revision: Changes made in Section 14.

Revised: 04-27-2022 Replaces: 01-13-2015

The data in this Safety Data Sheet relates to the specific material designated and does not relate to its use in combination with any other material or process. The data contained is believed to be correct. However, since conditions of use are outside our control it should not be taken as warranty or representation for which ELECTRO POLISH SYSTEMS, INC. assumes legal responsibility. This information is provided solely for your consideration, investigation, and verification.



Border States Electric - WIC 3800 W Dora St Wichita KS 67213-1211 Phone: 316-945-1313

> CENTRAL ELECTROPOLISHING 103 N LAWRENCE AVE ANTHONY KS 67003-2804

# Quote

Page: 1 of 1

BSE Quote: 26894607 Sold-To Acct #: 209511

Valid From: 01/19/2023 To: 01/26/2023 Payment Terms: Net 25th prox

Created By: James Thurber

Tel No: 316-226-7740

Fax No:

Inco Terms: FOB ORIGIN

Ship-to:

CENTRAL ELECTROPOLISHING 103 N LAWRENCE AVE ANTHONY KS 67003-2804

Cust Item	BSE Item	Material MFG - Description	Quantity		Price Per	UoM	Value
	000010	166651 SO0 - 6/4C-SOOW-BLK-2	<b>40</b> FT 50R		4,890.00 / 1,0	000 FT	195.60
	000020	<b>122230</b> LEV - 9452-P ANGL PLG KC STOCK	1 EA 14-50P 50A BLK 12	5/250V	56.83 / 1	EA	56.83
	000030	<b>2251658</b> THHN - SS-THHN-6-BLK-1	18 FT 19STR-CU-500R		1,120.00 / 1,0	20.16	
00	000040	<b>2585673</b> APPT - 8498 4-11/16 IN SC KC STOCK	1 EA Q CVR SGL RCPT	APPT	29.37 / 1	EA	29.37
				Total \$ State Tax \$ County Tax \$ Local Tax \$ Other Tax1 \$ Other Tax2 \$ Other Tax3 \$ Tax Subtotal \$	6.500 % 0.000 % 0.500 % 2.000 % 0.000 % 9.000 %	19.62 0.00 1.51 6.04 0.00 0.00	301.96 27.17
				Net Amount \$			329.13

# To access BSE's Terms and Conditions of Sale, please go to https://www.borderstateselectric.com

The quoted sales tax is an estimate only based upon the information provided in this quote and will be finalized at the time of Invoice based upon the material purchased, quantity purchased, and delivery location.

Shipping and handling fees in this quote are an estimate only and will be finalized at the time of Invoice.

All clerical errors contained herein are subject to correction. In the event of any cost or price increases from manufacturers or other suppliers, caused by, but not limited to, currency fluctuations, raw material or labor prices, fuel or transportation cost increases, and any import tariffs, taxes, fees, or surcharges, BSE reserves the exclusive right to change its pricing at the time of shipping and will provide notice of any such change to its customers prior to costs being incurred.

			к		
	i.				